

IP101+IP102 new firmware+driver v1-5.txt

Attached file is new version driver for IP101 and IP102 to solve the problem for virtual COM driver installation in different IP segment. You can do automatically. In this version you can do automatically.

For manual method please refer to "IP101 setting in different IP segment.pdf"

But you need to upgrade the firmware in IP101 to work with this new version driver.

The new version firmware is IPE101S_upgrade_V1.5_051704.hex file or IPE102S_upgrade_V1.5_051704.hex file.

Please run "setup.exe" in this directory and use "repair" (NOT modify) to upgrade your driver.